

Welcome to Oregon

And a Look at Our R06A Experience


Corey Withroe
Oregon DOT – 503 986 3339
corey.r.withroe@odot.state.or.us

Image 1:
R1 Inspection Team







Image 2: Steve Morgan CC BY-SA 4.0



Pentagon



Hexagon



Octagon



-Oregon-

Thank You

Bruce Johnson State Bridge Engineer
Kevin Chesnik, Applied Research Associates
FHWA, AASHTO and their representatives in attendance
Mike Goff, ODOT Region 2 Bridge Inspector,
Jeff Swanstrom, ODOT Senior Bridge Inspector (Ret.)
John Adkins, ODOT Region 4 Bridge Inspector,
Debera-Jean Murdoch, Procurement Coordinator,
Andrew Blower, ODOT Corrosion Protection Engineer
Liantao Xu, Region 1 Senior Bridge Designer,
George Bornstedt, Region 5 Senior Bridge Designer,
Bryan Mast, Region 3 Bridge Maintenance Manager
Benjamin King, Region 3 Senior Construction Coordinator
Our maintenance crews, and D&H Flagging.
Our contracting Partners, especially
Adam Carmichael at Infrasense
Paul Fuchs at ThermalStare
Dennis Sack, Yajai Tinkey, from Olson Engineering
The Reader/ Listener

Introduction

1. Background & our inventory
2. Our initial strategy
3. Results and case studies
4. How that initial strategy has changed during this process
5. The near future of NDE on bridge decks
6. Potential applications on tunnels



Image 3: FC inspection of NB Interstate Bridge

OREGON DOT Bridge Inspection coding guide

DECK SURVEY GUIDELINES²

Corrosion Related-

Determine whether the defects are in fact, “Corrosion Related”. If any of the following conditions exist, the bridge inspector needs to instigate the specified actions:


1. Concrete Deck Element is in **condition state 3**, chain drag and map the bridge deck.
2. Concrete Deck Element is in **condition state 4**, take cores and test quality of deck materials.

Condition state 3:

1. Delams/ Spall > 1”
2. Cracks: > 0.009” or < 1’ apart
3. Exposed rebar w/ measureable section loss
4. Rutting causing > 1” deep ponding
5. Coarse aggregate loose or popped out

Condition State 4:

1. Anything Warranting Structural Review



OREGON DOT Bridge Design Manual

QUANTITY ESTIMATES³

Class 2 Deck Preparation (SC Overlays only)

A deck survey is recommended to confirm the estimated quantity of both Class 2 and Class 3 Deck Preparation. Chain drag, *infrared scan, impact echo or ground penetrating radar* (GPR) [are] acceptable methods of performing a deck survey.

- **When at least the bottom half of deck is still sound**
- **~\$270/ yd² (2017 cost data)⁴**

Class 3 Deck Preparation (SC Overlays only)

- **When concrete beyond mid-depth needs removal**
- **~\$650/ yd²**




Figure 1 New Youngs Bay Elevation

	Deck			Superstructure			Substructure			Culvert#		
NBI Rating	<i>N</i>	μ	σ	<i>N</i>	μ	σ	<i>N</i>	μ	σ	<i>N</i>	μ	σ
Years at 8	1899	8.72	6.49	1970	11.45	7.55	2031	10.92	7.30	35	5.35	3.24
Years at 7	1354	12.12	6.55	1308	11.49	6.50	1372	11.51	7.05	91	6.49	3.23
Years at 6	230	9.13	5.75	154	9.20	5.35	232	9.28	5.69	85	6.80	3.05
Years at 5*	18	9.44	5.86	6	8.50	4.11	14	9.71	5.26	21	4.35	0.00
Years at 4*	21	5.52	3.38	10	2.70	5.50	18	6.33	4.29			

Included in *N* only if dropped

*Included if 4 is current rating

As of 2017 Federal Submittal

Table 1

only 10 years of data and included if current rating

Those still at 5 or below

Deck




Chart 1

SD Deck Count - 12 year dwell

As of 2017




Chart 2

Deck Elements Health Index by year and group

As of 2017




Chart 3

Figure 2

HI for Deck or Superstructure or Substructure

$$= \frac{\sum \{ \text{Element Quantity CS-1} * (1) + \text{Quantity CS-2} * (2/3) + \text{Quantity CS-3} * (1/3) \} * \text{Element Wt}}{\sum \{ \text{Total Element Quantity} * \text{Element Weight} \}}$$

Condition ● Fair ● Good ● Poor

Count of Condition
2754




Figure 3




Figure 4

“Network Level” High-Speed, GPR, IR, HD Video



“Project Level” Impact Echo & Chain Drag (with lane closure)





Figure 5

Costs



■ High-Speed surveys

■ Analysis

■ Mobilization/ Management

■ Field Validation

■ Traffic Control

Chart 4


Equipment used for Deck Evaluations

**GPR:**

- ASTM D6087-08
- Dual 2Ghz Horns, GSSI, Inc.
- 3' Transverse increments
- 40' = 13 lines
- May, July 2017
- 70°-87° F;
- 11:00AM – 6:30 PM
- 4 passes/ 2 lanes + shoulder
- ≤ 60 mph

IR:

- ASTM D4788-03 (2013)
- 640x480 FLIR Model A655sc
- Sony a7 4K camera
- May, July 2017
- 70°-87° F;
- 11:00AM – 6:30 PM
- 4 passes/ 2 lanes + shoulder
- ≤ 50 mph

IR Equipment




Figure 7




Figure 8

Initial Results – Thin Decks

1/3

BRIDGE_ID	YEARBUILT	MATERIALMAIN	DESIGNMAIN	DKSURFTYPE	DKRATING	Notes	INF_Del	INF_GPR	CS2	CS3	DK_HI
07832	1956	2 Concrete Continuous	04 Tee Beam 02	1 Monolithic Concrete	4	Severe transverse cracking throughout	16%	16%	83%	3%	71%
02193B	1962	5 Prestressed Concrete	Stringer/Girde r	1 Monolithic Concrete	4		3%	14%	19%	0%	94%
08306	1964	3 Steel	15 Movable - Lift	1 Monolithic Concrete	5		6%	29%	40%	1%	86%
09567	1971	6 P/S Conc Continuous	05 Multiple Box Beam	1 Monolithic Concrete	6		7%	22%	55%	1%	83%
08114	1958	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6	Large shadow from tree at west end of deck	3%	21%	70%	16%	
08363	1958	2 Concrete Continuous	04 Tee Beam	1 Monolithic Concrete	6	IR data limited due to extensive tree shadows.	10%	10%	3%	0%	
08254	1958	2 Concrete Continuous	04 Tee Beam	1 Monolithic Concrete	6		8%	14%	37%	2%	
07404	1955	3 Steel	09 Truss-Deck	1 Monolithic Concrete	6	Extensive cracking throughout	5%	7%	2%	0%	99%
17225	1993	5 Prestressed Concrete	05 Multiple Box Beam 02	1 Monolithic Concrete	6		6%	13%	50%	0%	85%
08167	1960	5 Prestressed Concrete	Stringer/Girde r	1 Monolithic Concrete	6		6%	8%	42%	0%	

Table 2

CS2 > GPR Defects, IR Delams > CS3

Initial Results – I-84 Chlorides

2/3

BRIDGE_ID	YEARBUILT	MATERIALMAIN	DESIGNMAIN	DKSURFTYPE	DKRATING	Notes	INF_Del	INF_GPR	CS2	CS3	DK_HI
09635A	1972	4 Steel Continuous	02 Stringer/Girder	1 Monolithic Concrete	5		8%	12%	58%	21%	78%
09632	1972	4 Steel Continuous	02 Stringer/Girder	5 Epoxy Overlay	6		9%	11%	1%	0%	100%
09632A	1972	4 Steel Continuous	02 Stringer/Girder	5 Epoxy Overlay	6		3%	9%	2%	0%	99%
02063	1969	4 Steel Continuous	02 Stringer/Girder	1 Monolithic Concrete	6		5%	20%	12%	0%	
02062B	1962	2 Concrete Continuous	05 Multiple Box Beam	3 Latex Concrete/Similar	7		5%	26%	25%	0%	
09631A	1972	2 Concrete Continuous	01 Slab	5 Epoxy Overlay	7		6%	26%	7%	0%	
09382	1969	4 Steel Continuous	02 Stringer/Girder	5 Epoxy Overlay	7		6%	17%	13%	0%	
19865	2004	4 Steel Continuous	02 Stringer/Girder	1 Monolithic Concrete	7		11%	10%	18%	0%	
20743	2009	5 Prestressed Concrete	05 Multiple Box Beam	1 Monolithic Concrete	7	Infrared effectiveness limited due to depth of rebar >4.5 inches	2%	10%	1%	1%	97%
20742	2009	5 Prestressed Concrete	05 Multiple Box Beam	1 Monolithic Concrete	7	Significant amount of debris along both shoulders	8%	5%	14%	5%	93%

Table 3

GPR Defects, IR Delams > CS2

09635A – Outlier, (CS2 cracking/ CS3 Rutting)

Initial Results – Others w/ Overlay

3/3



BRIDGE_ID	STRUCNAME	YEARBUILT	MATERIALMA AIN	DESIGNMA AIN	DKSURFTYPE	DKRATING	Notes	INF_ Del	INF_ GP R	CS2	CS3	DK_HI
17477	Hwy 1 over Turner-Sunnyside Rd	1997	6 P/S Conc Continuous	01 Slab	3 Latex Concrete/Similar	5		5%	6%	7%	1%	
01417N	Tualatin River, Hwy 1W NB	1955	2 Concrete Continuous	03 Girder- Floorbeam	3 Latex Concrete/Similar	5	A few large shadows from trees	10%	14%	6%	44%	69%
01377A	Columbia R & N Hayden Isl Dr, Hwy1 NB (Interstate)	1916	3 Steel	15 Movable - Lift	3 Latex Concrete/Similar	5	Patching primarily concentrated in the inside lanes of both directions.		19%	32%	2%	90%
07864A	Hwy 1 over 16th Street (Landess Rd)	1956	2 Concrete Continuous	04 Tee Beam	3 Latex Concrete/Similar	6		6%	9%	1%	14%	
08221A	Hwy 1 NB over Knox Butte Rd (North Albany Intchg)	1958	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6		4%	9%	4%	1%	
08221B	Hwy 1 NB over Hwy 58 NB (North Albany Intchg)	1958	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6		3%	10%	17%	5%	
07865A	Hwy 1 over Taylor Ave	1956	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6		7%	9%	2%	45%	75%
08828	Hwy 9 over POTB RR at MP 59.32	1962	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6	IR data limited due to extensive tree shadows.	7%	14%	11%	0%	
02349	Lake Lytle Outlet, Hwy 9	1938	7 Wood or Timber	02 Stringer/Gird er	3 Latex Concrete/Similar	6	Large shadow from tree in southbound lane	12%	13%	4%	0%	98%
07333	Columbia R & N Hayden Isl Dr, Hwy1 SB (Interstate)	1958	3 Steel	15 Movable - Lift	3 Latex Concrete/Similar	6	Truss structure obstructs deck from obtaining consistent solar heating	NA	8%	18%	9%	
08583	Hwy 1 over NE Hassalo St & NE Holladay St	1963	5 Prestressed Concrete	02 Stringer/Gird er	5 Epoxy Overlay	6		5%	14%	16%	4%	99%
08203B	Hwy 1 over SW 26th Ave	1959	2 Concrete Continuous	04 Tee Beam	3 Latex Concrete/Similar	6		7%	13%	31%	15%	
08227N	Oak Creek, Hwy 1 NB	1958	2 Concrete Continuous	04 Tee Beam	5 Epoxy Overlay	6		2%	7%	5%	0%	
02062A	Tanner Creek, Hwy 2 WB	1950	2 Concrete Continuous	02 Stringer/Gird er	3 Latex Concrete/Similar	7		4%	20%	36%	15%	79%

Table 4

CS2 > GPR Defects, IR Delams > CS3

Initial Results – Bridge 02071A

Coring indicates chloride content above initiation threshold—not indicated with high-speed GPR scans



Chloride Concentrations (Curve Fit, 6 Cores)
 Chart 5 Evaluation of in-service Bridge Decks using Chloride Analysis⁵

Figure 9




Figure 10



Image 4: Coring the NB Interstate Bridge




Chart 6 Evaluation of in-service Bridge Decks using Chloride Analysis⁵

Cores 3 & 4




Figure 12




Figure 13




Chart 6 Evaluation of in-service Bridge Decks using Chloride Analysis⁵

Cores 11,12




Figure 14

Cores 9,10

Coring indicates chloride content *below* initiation threshold—not indicated with high-speed GPR scans

4 samples (locations unknown)

ADT: 66,150 (NB Only)




Chart 7 Evaluation of in-service Bridge Decks using Chloride Analysis⁵




Figure 16

Results – Field Validation – Bridge 02349




Image 5: chain drag and impact echo on Br 023948

Figure 17

Results – Field Validation – Bridge 07832




Figure 18



Image 6




Figure 19




Image 7




Figure 20




Image 8




Figure 21

Results – Impact Echo Tools




Image 9

$$\text{Thickness} := \frac{C_{p_plate}}{2f}$$

Figure 22

“A typical velocity [C_{p_plate}] for concrete (12,000 ft/s)”

$$\begin{aligned} C_{p_plate} &= 0.96 C_p \\ &= 0.96 * P\text{-wave speed} \end{aligned}$$

ASTM C1383-15

P-Wave speed/ Thickness

Measurement in concrete slabs

Olson Instruments NDE 360 unit and CTG-2 unit




Image 10

Results – Field Validation

Bridge	Area surveyed (ft ²)	ODOT DELAM (ft ²)	% delam'ed	Matches Infrasense (ft ²)	% matching	% False negative	Infrasense Delam. (ft ²)	% delam'ed	Matches ODOT (ft ²)	% matching	% False Positive
01417N	6496	173	2.66%	64.8	37.5%	62.5%	740	11.39%	65	8.8%	91.2%
08958F	17340	40	0.23%	29	72.5%	27.5%	1018	5.87%	29	2.8%	97.2%
02349	1836	15	0.82%	3	20.0%	80.0%	268	14.60%	3	1.1%	98.9%
08828	2880	65	2.26%	54	83.1%	16.9%	288	10.00%	54.4	18.9%	81.1%
09382	27000	1629	6.03%	1284.4	78.8%	21.2%	3132	11.60%	1283.9	41.0%	59.0%
20742	2200	2	0.09%	0	0.0%	100.0%	150	6.82%	0	0.0%	100.0%
08254	2238	115	5.14%	69.4	60.3%	39.7%	96	4.29%	70.1	73.0%	27.0%
17225	4830	2	0.04%	0.5	25.0%	75.0%	278	5.76%	1	0.4%	99.6%
07832	3312	102	3.08%	14	13.7%	86.3%	261	7.88%	14.8	5.7%	94.3%
07404	13200	75	0.57%	12	16.0%	84.0%	596	4.52%	11.2	1.9%	98.1%

Table 5

Chain Drag Results vs Infrared Scanning to determine delamination quantities/ location

November 27- December 2, 2017

Measurements ±10%

**Routine Inspection:
Thin Overlay Recommended
(CS2 Efflorescence
Polished aggregates in wheel paths
Extensive CS1 Cracking)**



Image 12

SOUTH UMPQUA RIVER (VETS) - BR# 07404 - HWY 1 SB - MP: 124.54

ON-LINE ROADWAY VIEW



Image 13

SOUTH UMPQUA RIVER (VETS) - BR# 07404 - HWY 1 SB - MP: 124.54

SIDE ELEVATION

**Deck sealed
previously**




Figure 23







Figure 24

Concrete Condition Legend		Orientation	Quantity Summary		General Information	
			Condition	sq. ft.	%	
Deterioration detected by GPR	Delamination detected by IR	 Direction of traffic	Delamination (IR)	1611	5.5	Bridge ID: 07404
⊕ IE (delam)	Patching		Deterioration (GPR)	2084	7.1	I-5 SB over S Umpqua R
⊕ IE (no delam)	Not detectable by IR / GPR		Patching (Visual)	NA	0.0	Analyzed by: GC/JC
⊕ IE (no delam)						Reviewed by: EG
						Completer: 1 of 3
						Sheet 1 of 1





Concrete Condition Legend		Orientation	Quantity Summary		General Information		
			Condition	sq. ft.	%		
Deterioration detected by GPR	Delamination detected by IR	 ▶ Direction of traffic	Delamination (IR)	1611	5.5	Bridge ID: 07404 I-5 SB over S Umpqua R	
Severity (color scale)	Patching		Deterioration (GPR)	2084	7.1	Analyzed by: GC/JC Reviewed by: EG Completed: 01/20/17	
⊕ IE (delam)	Not detectable by IR / GPR		Patching (Visual)	NA	0.0	Sheet 2 of 3	
⊕ IE (no delam)							

What is this?




Figure 27 Exposed rebar 1' x 2' 1' x 2' Exposed rebar 1' x 1' 1' x 1' spall 1' x 1' No delaminations detected

Delamination detected by ODOT chain drag survey 12/1

I didn't see anything on the surface. I dragged my chain over it several times,

Although this isn't the exact spot, this could be what's going on (report recommended patching several like it)



Image 11

Conditions: 42°, foggy, moderate fast traffic




Figure 28

Delamination detected by ODOT chain drag survey 12/1
 Other Notes 12/1
 Not surveyed 12/1

Vets Bridge (I-5 near Roseburg)
 Monolithic Concrete – Deck Truss





Figure 29



Concrete Condition Legend		Orientation	Quantity Summary		General Information	
			Condition	sq. ft.	%	
Deterioration detected by GPR	Delamination detected by IR	 Direction of traffic	Delamination (IR)	1611	5.5	Bridge ID: 07404
IE (delam)*	Patching		Deterioration (GPR)	2084	7.1	I-5 SB over S Umpqua R
IE (delam)	Not detectable by IR / GPR		Patching (Visual)	NA	0.0	Analyzed by: GC/JC
IE (no delam)						Reviewed by: EC
						Complete 3 of 3
						Sheet 1 of 1





**Shade from a
Cottonwood (?)
South end
~ 6pm summertime**

Google

Image 12

Hairline map cracking prior to seal



Image 13



Image 14

Spall with exposed rebar appears as Delam of different shape on map




Figure 30




Image 15

VETS Bridge	ODOT ₁	ODOT ₂	Vendor ₁				Final Repair
Southbound Only	Chain Drag SB	Routine	Infrared		GPR		SB
Bridge 08203B	Field Data	Inspection	Field Data	Calibrated	Field Data	Calibrated	
Area Surveyed	13200	37039	29300	13200	29300	29300	37039
Delam/Deteriorated	75	15	1573.6	596	2084	2084	390
% Delam/ Deteriorated	0.57%	0.04%	5.37%	4.52%	7.1%	7.1%	1.05%
Match	12			11.2			
% Matching	16.0%			1.9%			
False Negative	84.0%						
False Positive				98.1%			

Table 6

Most repairs on south side of bridge, no class 3 prep



Image 16

Conclusions:

**NDE estimates >
actual quantities >
chain drag**



Image 17

**Thin wearing surface (25% CS3)
40 ft² of CS2 Spalls
1985 overlay
PPC overlay sometime since**








Image 18: Looking west toward Moda Center



Image 19

Figure 31



	Test location - Distressed area	TOT 5
	Test location - Edge of Distressed area	TOT 4
	Test location - Non-Distressed area	TOT 2
	Test location - Between cluster of markings	TOT 1
		<u>TOTAL 12 TESTS</u>

- | | | | |
|---|--|---|--|
| ① | Epoxy failed | ⑦ | 128 psi |
| ② | Core broke during drilling ~2" below overlay | ⑧ | Core broke during hand tightening of rod into puck |
| ③ | 146 psi Core broke ~2" below overlay | ⑨ | 47 psi |
| ④ | 158 psi | ⑩ | 143 psi |
| ⑤ | Core broke during drilling ~2" below overlay | ⑪ | Core broke during drilling ~1 1/2" below overlay |
| ⑥ | 74 psi Core broke ~1 3/4" below surface | ⑫ | 16 psi |

Better Delamination Correlation
14% Delamination





Figure 32

Note slight shifting of well-established patching locations

Conclusions: SB Deck to be replaced (2021)

IR-UTD



Conventional IR




Figure 33

**Conventional (static) Infrared vs
Long-term Infrared**




Figure 34

Infrared- "Ultra Time Domain"

**Principle: two day/night cycles rather than a sliver of time
To create time-lapsed thermal measurements**





Figure 35

Core locations

- **Chain drag dramatically under-detects defects**
- **Intact cores agreed with IR results**



**Routine
Inspection:
Top Flange**

- **3% CS3 (rust staining)**
- **12% CS2 (soffit cracking)**
- **Spalls, exposed rebar**
- **LMC overlay Sealed (2104)**
- **Column spalls & cracks**

Image 20

Three options for bridge based (in part) on NDE results

- 1. Replace the overlay if deck is sound**
- 2. Apply PPC overlay to extend life 15-20 years**
- 3. Replace the entire bridge**

- **Two, 2-3 hour shoulder closures**
 - **\$1800**
- **48 Hour duration**



Image 21

- **Significantly more expensive than high-speed**
- **~\$1.75/ft²**
vs
- **~¢1.75/ft²**



Image 22




Figure 36

- Chain drag, coring also performed (outside R06A)
- One sample used to calibrate IR-UTD





Figure 37






Image 25

Processed for surface defects




Image 24

Processed for subsurface structural details




Image 26

Structural view with identified defects




Image 27

Processed for surface defects




Figure 38



Image 28

- **3rd Party Inspection ~25% delaminated:**
 - NB: 1700 ft² of Delamination
 - SB: 1400 ft² of Delamination
 - 0.007% - 0.022% chlorides from core samples
 - (deemed not sufficiently close to the 0.04% threshold)
 - 4,000 – 8,600 psi
- **Long Term Infrared (~5.6% delaminated, more precisely drawn)**
 - NB: 500 ft²
 - SB: 460 ft²
 - Core sample sent to potentially calibrate depth of delamination
- **Recall High-speed infrared (~7% delaminated, 13% defect by GPR)**

Q: How long is the coast of Britain?

A: It depends on the size of your measuring stick.

(Why it would be helpful to have an agreed upon standard)

Conclusions:

- **Chain drag/ coring and long-term IR make the Same recommendation: replace structural overlay**
- **But: because of life cycle costs/ roadway & traffic control**
 - **ADT: 121,000**
- **Decision was made to replace whole structure with thicker deck**
- **So we won't actually get a direct relation to quantities**
- **We will get a cost-effective bridge**




Image 29

Routine Inspection: RC Deck

- **30% CS2 (Delamination, cracking, rutting)**
- **1% CS3 (Exposed rebar, cracking)**


Image 31




Image 30

Maintenance Recommendations:

- **Rehab deck (2017)**
- **Patch spalls/exposed rebar (2007)**



DRAWING KEY					
	Delamination		Abrasion/Rutting		SEALED DECK AREA
	Spall		Efflorescence (CS 2)		PHOTO LOCATION (#)
	Patched Area		Efflorescence (CS 3)		
	Exposed Rebar		Deck Cracking		



- 1. 2'X1' delamination with exposed rebar (2-SF)
- 2. 1' Ø delamination (1-SF)
- 3. 3'X1' hollow sounding concrete (3-SF)
- 4. 2'X1' shallow spall with exposed rebar (2-SF)
- 5. 1'X1' shallow spall with exposed rebar (1-SF)
- 6. 2'X1' shallow spall with exposed rebar (2-SF)
- 7. 3'X1' hollow sounding concrete (3-SF)

- 8. 1'X1' delamination (1-SF)
- 9. 1'X1' delamination with exposed rebar (1-SF)
- 10. 1'X1' delamination (1-SF)
- 11. 3'X1' delamination with exposed rebar (3-SF)
- 12. 1'X1' shallow spall with exposed rebar (1-SF)
- 13. 1'X1' shallow spall with exposed rebar (1-SF)
- 14. 3'X1' shallow spall with exposed rebar (3-SF)
- 15. 1'X1' delamination (1-SF)
- 16. 2'X1' delamination with exposed rebar (2-SF)

Figure 39




Figure 40

- **1% CS3 (Exposed rebar, cracking)**

DRAWING KEY					
	Delamination		Abrasion/Rutting		SEALED DECK AREA
	Spall		Efflorescence (CS 2)		
	Patched Area		Efflorescence (CS 3)		
	Exposed Rebar		Deck Cracking		PHOTO LOCATION (#)




Figure 41




Figure 42




Figure 43




Figure 44

DRAWING KEY					
	Delamination		Abrasion/Rutting		SEALED DECK AREA
	Spall		Efflorescence (CS 2)		PHOTO LOCATION (#)
	Patched Area		Efflorescence (CS 3)		
	Exposed Rebar		Deck Cracking		




Figure 45




Figure 46




Chart 7 Evaluation of in-service Bridge Decks using Chloride Analysis⁵

Cores 3, 4




Figure 47

Lift span interference




Chart 7 Evaluation of in-service Bridge Decks using Chloride Analysis⁵

Cores 1, 2





Figure 48

Conclusions:

Chain Drag Quantities:

219 ft² delams	(0.1%)
322 ft² Exposed Rebar	(0.1%)
1400 ft² CS3 Cracking	(0.5%)
34,800 ft² CS2 Cracking	(13%)

High-Speed:

1676 ft² Delam (IR)	(6%)
78,000 ft² Defective (GPR)	(29%)

Solution

**Overlay (awaiting quantities)
& Cathodic Protection**



Image 32



Image 33



Image 34

Traffic noise proved to limit effectiveness of the human ear as a sensor—with or without earplugs.

(NRR 29 are standard earplugs, which reduces noise level $(29-7)/2 = 11$ dB and performance is better at High-frequency sound (8000 Hz vs. 125 Hz.)

“Flexural oscillation of a delaminated area is typically in a 1 to 3 kHz Range.”⁶

Manual Sounding – Note earplugs



Image 35

Sounding





Figure 49



Figure 50

Robot-Assisted Bridge Inspection Tool

5 instruments for recording; 1 laser scanner for navigation



Ultrasonic Surface Wave
ksi (lower is worse)

Figure 51

Electric Resistivity
kOhm (High Resistivity is Worse)





Figure 52



Impact Echo
Hz (lower is worse)

Figure 53




Figure 54

GPR

dB (lower = less cover)

Cover Depth

(In.) Can we get to ± 0.5 inches?




Figure 55



Figure 55

Repair Areas

Serious, Poor

Fair, Good = CS1, 2, 3, 4, etc.? Or Class 1, 2, 3 removal?

- Our current platforms can fly for approx. 20 mins per battery set
- We do not own a thermal camera at this point, but the off the shelf option is a FLIR XT camera @ \$10k
- Photos can be shot at a fixed interval and analyzed on free desktop software provided by FLIR
- We are just starting to research the idea of a tethered UAS option. This would allow for a constant power and data feed to keep the UAS in the air for extended periods of time. I am submitting a research proposal to study the effectiveness of this solution.

*-Christopher Harris PE,
ODOT Engineering Automation*

Wind and airspace restrictions remain limiting factors for drone inspection – not the cameras or the payload capacity



Southern bent pin connection. Taken from senseFly albris main HD camera. Focal length: 8 mm, 35mm equivalent: 25 mm. (Full image)

Conclusions

- Network-wide strategies and **high-speed methods are not in our near-future**, full-scale implementation plans
- That said, we are **still calibrating the raw data** for more **meaningful definitions** and precise, reliable defect quantities
 - Shared interest between agencies and contractors in fine-tuning data → defect translations.
- We have already seen how more intensive **NDE methods can inform specific decisions on bridges for which there is planned work** and avoid large quantity-related, change order costs (on the order of \$100,000)
- **Thankful** for the opportunity to explore these options and learn from other states

Questions for the group

- 1. Have you discovered reliable techniques for determining depth of delamination (below half thickness)?**
- 2. Do you have well-defined contract or procedure language for you results?**
 1. What does “good”, “fair”, “poor”, “severe” mean?
 2. How do you otherwise interpret or quantify these terms?
- 3. Your best methods for sharing these results with other parts of your agency?**
- 4. Any recommendations on standardizing?**
 1. Units of measurement
 2. Environmental limitations

Questions



Suzhou, China

References

1. Oregon Department of Transportation, *Bridge Inspection Coding Guide*, March 2015 (p. 230)
https://www.oregon.gov/ODOT/Bridge/Documents/Bridge_manuals/codingguide2015.pdf
2. Oregon Department of Transportation, *Bridge Design Manual*
May 2018 (§1.9.4.10) <https://www.oregon.gov/ODOT/Bridge/Pages/Bridge-Design-Manual.aspx>
3. Oregon Department of Transportation, *Bridge Cost Data 2017*
FY 2017 ftp://ftp.odot.state.or.us/Bridge/CostData/CostDataBook2017/cost_data_2017.pdf
4. Blower, Andrew S. *Evaluation of in-service Bridge Decks using Chloride Analysis*
Oregon Department of Transportation SHRP2 R19A Service Life Design Study – Phase II, 2017
5. Federal Highway Administration Research and Technology, Non Destructive Evaluation Web Manual
https://fhwaapps.fhwa.dot.gov/ndep/DisplayTechnology.aspx?tech_id=16
6. Gillins, Daniel T. Parrish, Christopher, Gillins, Matthew, Simpson, Chase *Eyes in the Sky: Bridge Inspections with Unmanned Aerial Vehicles* 2018
https://www.oregon.gov/ODOT/Programs/ResearchDocuments/SPR787_Eyes_in_the_Sky.pdf